

# Product Safety Recall



## **Kubota Z400 Series Mower**

**Z411KW-48-AU (serial nos. 10113 - 10302)**

**Z421KW-54-AU (serial nos. 10079 - 10258)**

- Defect:** The ROPS retention bolts may not have been torqued during the final assembly process.
- Hazard:** Under some operating conditions, the ROPS retention bolts can become loose, putting the operator at risk of injury.
- What to do:** Mower owners should immediately stop using the affected vehicles and contact their Kubota dealer who will schedule an inspection of the mower ROPS retention bolts torque at no charge.
- Contact details:** You can contact your Kubota dealership or contact Kubota Tractor Australia on 03 9394 4400 or go to [www.kubota.com.au](http://www.kubota.com.au) for further information.

**See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information**